




Specify Part No. by required I.D., O.D., and Length.  
 (e.g.) I.D. is 44mm, O.D. is 56mm, and length is 51mm.

**55S - 445651**  
**Parts No.**



● Please refer to page 250 for the method for oil-bearing treatment.

Parts No.	I.D.		O.D.		Length	
	φd	Tolerance	φD	Tolerance	L	Tolerance
<b>55S-193126</b>	19	$\begin{smallmatrix} +0.3 \\ -0.5 \end{smallmatrix}$	31	$\begin{smallmatrix} +0.3 \\ -0.5 \end{smallmatrix}$	26	$\begin{smallmatrix} +3.0 \\ 0 \end{smallmatrix}$
<b>55S-243631</b>	24	$\begin{smallmatrix} +0.3 \\ -0.5 \end{smallmatrix}$	36	$\begin{smallmatrix} +0.3 \\ -0.5 \end{smallmatrix}$	31	$\begin{smallmatrix} +3.0 \\ 0 \end{smallmatrix}$
<b>55S-284846</b>	28	$\begin{smallmatrix} 0 \\ -1.2 \end{smallmatrix}$	48	$\begin{smallmatrix} +1.2 \\ 0 \end{smallmatrix}$	46	$\begin{smallmatrix} +3.0 \\ 0 \end{smallmatrix}$
<b>55S-294141</b>	29	$\begin{smallmatrix} +0.3 \\ -0.5 \end{smallmatrix}$	41	$\begin{smallmatrix} +0.3 \\ -0.5 \end{smallmatrix}$	41	$\begin{smallmatrix} +4.0 \\ 0 \end{smallmatrix}$
<b>55S-344641</b>	34	$\begin{smallmatrix} +0.3 \\ -0.5 \end{smallmatrix}$	46	$\begin{smallmatrix} +0.3 \\ -0.5 \end{smallmatrix}$	41	$\begin{smallmatrix} +4.0 \\ 0 \end{smallmatrix}$
<b>55S-345151</b>	34	$\begin{smallmatrix} 0 \\ -1.2 \end{smallmatrix}$	51	$\begin{smallmatrix} +1.2 \\ 0 \end{smallmatrix}$	51	$\begin{smallmatrix} +4.0 \\ 0 \end{smallmatrix}$
<b>55S-395651</b>	39	$\begin{smallmatrix} +0.3 \\ -0.5 \end{smallmatrix}$	56	$\begin{smallmatrix} +1.2 \\ 0 \end{smallmatrix}$	51	$\begin{smallmatrix} +4.0 \\ 0 \end{smallmatrix}$
<b>55S-445651</b>	44	$\begin{smallmatrix} +0.3 \\ -0.5 \end{smallmatrix}$	56	$\begin{smallmatrix} +1.2 \\ 0 \end{smallmatrix}$	51	$\begin{smallmatrix} +4.0 \\ 0 \end{smallmatrix}$
<b>55S-496661</b>	49	$\begin{smallmatrix} 0 \\ -1.2 \end{smallmatrix}$	66	$\begin{smallmatrix} +1.2 \\ 0 \end{smallmatrix}$	61	$\begin{smallmatrix} +4.0 \\ 0 \end{smallmatrix}$
<b>55S-517361</b>	51	$\begin{smallmatrix} 0 \\ -1.2 \end{smallmatrix}$	73	$\begin{smallmatrix} +1.2 \\ 0 \end{smallmatrix}$	61	$\begin{smallmatrix} +4.0 \\ 0 \end{smallmatrix}$
<b>55S-547661</b>	54	$\begin{smallmatrix} 0 \\ -1.2 \end{smallmatrix}$	76	$\begin{smallmatrix} +1.2 \\ 0 \end{smallmatrix}$	61	$\begin{smallmatrix} +4.0 \\ 0 \end{smallmatrix}$
<b>55S-568161</b>	56	$\begin{smallmatrix} 0 \\ -1.2 \end{smallmatrix}$	81	$\begin{smallmatrix} +1.2 \\ 0 \end{smallmatrix}$	61	$\begin{smallmatrix} +4.0 \\ 0 \end{smallmatrix}$