

Oiles Cermet M Bushing Material







 Oil impregnation is necessary by referring to the oil impregnation method, page 246 when you machined the plate.

Parts No.	I.D.		0.D.		Length	
	φd	Tolerance	φD	Tolerance	L	Tolerance
548-092333	9	+0.5 -0.3	23	+0.6 -0.2	33	+3.0 0
548-142631	14	+0.5 -0.3	26	+0.8 0	31	+3.0
548-153131	15	+0.5 -0.3	31	+0.6 -0.2	31	+3.0 0
548-244133	24	+0.5 -0.3	41	+0 <u>.</u> 8	33	+3.0 0
548-294136	29	+0.5 -0.3	41	+0.8 0	36	+3.0 0
548-294933	29	+0.5 -0.3	49	+0.6 -0.2	33	+3.0 0